

NOTICE TO MARINERS

No. H. 69/2018

U P P E R H U M B E R

SHOAL WATER

MARINERS ARE WARNED that a survey carried out on the 1st May 2018 shows the following: -

- 1) A least depth of 0.2 metres below Chart Datum exists close North of the ships course 315 metres downstream of the Lower Whitton Light Float.

Deeper water exists on and to the South of the ships course in this vicinity.

- 2) A least depth of 0.1 metres **ABOVE** Chart Datum exists South of the ships course 160 metres downstream of the No. 33A Light Float.

Deeper water exists on the ships course in this vicinity.

- 3) A least depth of 0.1 metres **ABOVE** Chart Datum exists close North of the ships course 415 metres upstream of the No. 32C Light Buoy.

Deeper water exists on the ships course in this vicinity.

MARINERS ARE ADVISED that 0.2 metres **ABOVE** Chart Datum should be used for passage planning purposes and the shoal water referred to in Notice to Mariners No. H. 62/2018 is no longer valid.

CAPT. A. FIRMAN
HARBOUR MASTER, HUMBER

1st May 2018

THE INTERNET

In order to widen communication between ABP Humber Estuary Services and those with an interest in the estuary, you are invited to visit our website which carries a wide range of information, including current live weather and Buoy positions, charts, tidal information and copies of this and other Notice to Mariners.

www.humber.com