
NOTICE TO MARINERS

No. H. 72/2018

RIVER HUMBER

HESSLE SAND - SHOAL WATER

MARINERS ARE WARNED that a survey carried out on the 9th May 2018 shows the following:

- 1) A least depth of 0.8 metres **ABOVE** Chart Datum exists close North of the ships course 135 metres upstream of the No. 23 Light Buoy.

Deeper water exists to the South in this vicinity.

- 2) A least depth of 0.2 metres **ABOVE** Chart Datum exists on the ships course from 40 metres downstream to 250 metres upstream of the No. 23 Light Buoy.

Deeper water exists to the South in this vicinity.

MARINERS ARE ADVISED that 0.8 metres **ABOVE** Chart Datum should be used for passage planning purposes and that the shoal water referred to in Notice to Mariners No. H. 52/2018 is no longer valid.

CAPT. A FIRMAN
HARBOUR MASTER, HUMBER

10th May 2018

THE INTERNET

In order to widen communication between ABP Humber Estuary Services and those with an interest in the estuary, you are invited to visit our website which carries a wide range of information, including current live weather and Buoy positions, charts, tidal information and copies of this and other Notice to Mariners.

www.humber.com