
NOTICE TO MARINERS

No. H. 76/2018

HUMBER APPROACHES

UNDERWATER OBSTRUCTION

MARINERS ARE WARNED that surveys carried out on the 27th of April 2018 and 3rd May 2018 show the following: -

An obstruction with a least depth of 13.9 metres below Chart Datum exists 335 metres South West of the No.3 Chequer South Cardinal Buoy in position:

Latitude 53° 32.936' N Longitude 000° 10.427' E (WGS 84)

MARINERS ARE ADVISED to navigate with caution in this area.

CAPT. A. FIRMAN
HARBOUR MASTER, HUMBER

11th May 2018

THE INTERNET

In order to widen communication between ABP Humber Estuary Services and those with an interest in the estuary, you are invited to visit our website which carries a wide range of information, including current live weather and Buoy positions, charts, tidal information and copies of this and other Notice to Mariners.

www.humber.com