

NOTICE TO MARINERS

No. H. 87/2018

RIVER HUMBER

HUMBER APPROACHES – CHANGE OF WRECK DEPTH

MARINERS ARE WARNED that surveys carried out between the 20th June 2017 and 3rd May 2018 show the following: -

- 1) A wreck with a least depth of 11.1 metres below Chart Datum exists 615 metres South South West of the South East Chequer Light Float in position:

Latitude 53° 33.079' N Longitude 000° 12.557' E (WGS84)

- 2) A wreck with a least depth of 11.3 metres below Chart Datum exists 351 metres West South West of the Spurn Light Float in position:

Latitude 53° 33.325' N Longitude 000° 13.870' E (WGS84)

MARINERS ARE ADVISED to navigate with caution in this area.

**CAPT. A. FIRMAN
HARBOUR MASTER, HUMBER**

24th May 2018

THE INTERNET

In order to widen communication between ABP Humber Estuary Services and those with an interest in the estuary, you are invited to visit our website which carries a wide range of information, including current live weather and Buoy positions, charts, tidal information and copies of this and other Notice to Mariners.

www.humber.com