

---

# **NOTICE TO MARINERS**

---

**No. H. 89/2019**

## **RIVER HUMBER**

### **NO. 16 SAND END LIGHT FLOAT - RETURNED TO STATION**

**MARINERS ARE ADVISED** that the No.16 Sand End Light Float has been returned to station in its original charted position as follows:

Latitude: 53° 42.623' N      Longitude: 0° 14.504 W

Characteristics: FI R.4s

**MARINERS ARE FURTHER ADVISED** that Notice to Mariners No. H. 164/2018 is hereby cancelled.

**CAPT. A. FIRMAN  
HARBOUR MASTER, HUMBER**

02 July 2019

#### **THE INTERNET**

In order to widen communication between ABP Humber Estuary Services and those with an interest in the estuary, you are invited to visit our website which carries a wide range of information, including current live weather and Buoy positions, charts, tidal information and copies of this and other Notice to Mariners.