
NOTICE TO MARINERS

No. H. 93/2019

RIVER HUMBER

TEMPORARY REPLACEMENT OF NO. 4A CLEE NESS LIGHT FLOAT

MARINERS ARE ADVISED that the No. 4A Clee Ness Light Float has been removed for routine maintenance. In its charted position, a temporary red can buoy has been deployed which features the same light characteristics as the float, but no name boards are present.

Position: 53° 35.015' N 0° 01.670' E (WGS 84)

Characteristics: Fl(2)R.10s

MARINERS ARE REQUESTED to exercise care and caution when navigating in this vicinity.

**CAPT. A. FIRMAN
HARBOUR MASTER, HUMBER**

9th July 2019

THE INTERNET

In order to widen communication between ABP Humber Estuary Services and those with an interest in the estuary, you are invited to visit our website which carries a wide range of information, including current live weather and Buoy positions, charts, tidal information and copies of this and other Notice to Mariners.

www.humber.com