
NOTICE TO MARINERS

No. H. 96/2016

RIVER HUMBER

HALTON MIDDLE - SHOAL WATER

MARINERS ARE WARNED that a survey carried out on the 11th August 2016 shows the following:-

- 1) Depths of between 4.8 metres and 5.5 metres below Chart Datum have encroached up to 175 metres into the East side of the channel, from upstream of the No. 15A Light Buoy to 475 metres downstream of the No. 17 North Holme West Cardinal Light Float.

Deeper water exists to the West in this vicinity.

- 2) Depths of between 4.8 metres and 5.5 metres below Chart Datum have encroached up to 180 metres into the West side of the channel, from 1600 metres downstream to 250m upstream of the No. 14 Skitter Haven Light Buoy.

Deeper water exists to the East in this vicinity.

MARINERS ARE ADVISED that Notice to Mariners No. H. 38/2016 is hereby cancelled.

CAPT. A. FIRMAN
HARBOUR MASTER, HUMBER

12th August 2016

THE INTERNET

In order to widen communication between ABP Humber Estuary Services and those with an interest in the estuary, you are invited to visit our website which carries a wide range of information, including current live weather and Buoy positions, charts, tidal information and copies of this and other Notice to Mariners.

www.humber.com