

NOTICE TO MARINERS

No. H. 99/2016

RIVER HUMBER

FOUL HOLME CHANNEL - SHOAL WATER

MARINERS ARE WARNED that a survey carried out on the 18th August 2016 shows the following:-

A least depth of 0.9 metres below Chart Datum exists on the Eastern edge of the channel between the FH5 and FH3 Light Buoys.

Deeper water exists to the West in this vicinity.

MARINERS ARE ADVISED that Notice to Mariners No. H. 37/2016 is hereby cancelled.

**CAPT. A. FIRMAN
HARBOUR MASTER, HUMBER**

19th August 2016

THE INTERNET

In order to widen communication between ABP Humber Estuary Services and those with an interest in the estuary, you are invited to visit our website which carries a wide range of information, including current live weather and Buoy positions, charts, tidal information and copies of this and other Notice to Mariners.

www.humber.com