
NOTICE TO MARINERS

No. H. 61/2023

RIVER HUMBER

BULL CHANNEL - SHOAL WATER

MARINERS ARE WARNED that a survey carried out on the 17th May 2023 shows the following:-

- 1) Depths of between 2.4 metres and 5.5 metres below Chart Datum have encroached up to 285 metres into the Southern edge of the channel, from 905 metres upstream of the Bull Light Float (North Cardinal) to 290 metres downstream of the Bull Sand Light Buoy.

Deeper water exists to the North in this vicinity.

- 2) A shoal with depths of between 2.4 metres and 5.5 metres below Chart Datum extends from 650 metres downstream to 1615 metres upstream of the North Fort Cardinal Buoy.

MARINERS ARE ADVISED that Notice to Mariners No. H. 45/2023 is hereby cancelled.

**CAPT. A. FIRMAN.
HARBOUR MASTER, HUMBER**

18th May 2023

THE INTERNET

In order to widen communication between ABP Humber Estuary Services and those with an interest in the estuary, you are invited to visit our website which carries a wide range of information, including current live weather and Buoy positions, charts, tidal information and copies of this and other Notice to Mariners.

www.humber.com