
NOTICE TO MARINERS

No. H. 10/2023

UPPER HUMBER

No. 30 LIGHT FLOAT TEMPORARY REPLACEMENT

MARINERS ARE ADVISED that the No. 30 Light Float has been removed from station for maintenance. A Red Light Float with the same characteristics is being used as a temporary replacement in its charted position until further notice.

- Red Light Float
- Light Characteristics – Fl.R.4s
- Position – 53° 41.950' N, 0° 28.695' W (WGS84)
- Riding Light
- No Name Board is Present

MARINERS ARE ADVISED to navigate with caution in this vicinity.

CAPT. A. FIRMAN
HARBOUR MASTER, HUMBER

26th January 2023

LOCAL NOTICE TO MARINERS FOR 2020, 2021, 2022 & 2023 CURRENTLY IN FORCE:

H. 43/2020, H. 07/2021, H. 24/2021, H. 43/2021, H. 92/2021, H. 109/2021, H. 179/2021, H. 08/2022, H. 28/2022, H. 37/2022, H. 68/2022, H. 75/2022, H. 111/2022, H. 115/2022, H. 120/2022, H. 131/2022, H. 154/2022, H. 159/2022, H. 166/2022, H. 168/2022, H. 172/2022, H. 173/2022, H. 178/2022, H. 179/2022, H. 182/2022, H. 183/2022, H. 185/2022, H. 186/2022, H. 189/2022, H. 02/2023, H. 03/2023, H. 07/2023, H. 09/2023, H. 10/2023.

THE INTERNET

In order to widen communication between ABP Humber Estuary Services and those with an interest in the estuary, you are invited to visit our website which carries a wide range of information, including current live weather and Buoy positions, charts, tidal information and copies of this and other Notice to Mariners.
www.humber.com