
NOTICE TO MARINERS

No. H. 118/2024

RIVER HUMBER

BULL CHANNEL - SHOAL WATER

MARINERS ARE WARNED that surveys carried out on the 23rd and 24th September 2024 show the following:-

- 1) Depths of between 2.6 metres and 5.5 metres below Chart Datum have encroached up to 387 metres into the Southern edge of the channel, from 992 metres upstream of the Bull Light Float (North Cardinal) to 263 metres downstream of the Bull Sand Light Buoy.

Deeper water exists to the North in this vicinity.

- 2) A shoal with depths of between 2.6 metres and 5.5 metres below Chart Datum extends from 800 metres upstream of the Bull Light Float (North Cardinal) to 522 metres upstream of the Bull Sand Light Buoy.

- 3) Depths of less than 5.5 metres below Chart Datum have encroached up to 25 metres into the Northern edge of the channel from 45 metres to 320 metres upstream No. 5A Light Buoy.

Deeper water exists to the South in this vicinity.

MARINERS ARE ADVISED that Notice to Mariners No. H. 78/2024 is hereby cancelled.

**CAPT. A. FIRMAN.
HARBOUR MASTER, HUMBER**

25th September 2024

THE INTERNET

In order to widen communication between ABP Humber Estuary Services and those with an interest in the estuary, you are invited to visit our website which carries a wide range of information, including current live weather and Buoy positions, charts, tidal information and copies of this and other Notice to Mariners.

www.humber.com