
NOTICE TO MARINERS

No. H. 123/2024

UPPER HUMBER

SHOAL WATER

MARINERS ARE WARNED that a survey carried out on the 21st October 2024 shows the following:

- 1) A least depth of 1.0 metres **ABOVE** Chart Datum exists North of the ships course 225 metres downstream of the Lower Whitton Light Float.

Deeper water exists on the ships course in this vicinity.

- 2) A least depth of 0.1 metres **ABOVE** Chart Datum exists close North of the ships course 235 metres downstream of the No.32A Light Float.

Deeper water exists on the ships course in this vicinity.

- 3) Depths of between 0 metres at Chart Datum to 0.8 metres **ABOVE** Chart Datum exist North of the ships course from 430 metres downstream to 90 metres upstream of the No.32A Light Float.

Deeper water exists on the ships course in this vicinity.

- 4) A least depth of 0 metres at Chart Datum exists South of the ships course 270 metres downstream of the No. 32B Light Float.

Deeper water exists on and to the North of the ships course in this vicinity

MARINERS ARE ADVISED that 0 metres at Chart Datum should be used for passage planning purposes and that Notice to Mariners No. H. 120/2024 is hereby cancelled.

CAPT. A. FIRMAN
HARBOUR MASTER, HUMBER

22nd October 2024

THE INTERNET

In order to widen communication between ABP Humber Estuary Services and those with an interest in the estuary, you are invited to visit our website which carries a wide range of information, including current live weather and Buoy positions, charts, tidal information and copies of this and other Notice to Mariners.