
NOTICE TO MARINERS

No. H. 133/2021

HUMBER APPROACHES

INNER TRAFFIC SEPARATION SCHEME (INBOUND LANE) - SHOAL WATER

MARINERS ARE WARNED that surveys carried out between the 17th and 18th August 2021 show the following: -

- 1) Depths of between 7.4 metres below Chart Datum and 10.7 metres below Chart Datum have encroached up to 150 metres into the Northern buoy-line of the Inward Traffic Separation Scheme lane, from 800 metres East North East of the No. 3 Chequer South Cardinal Buoy to the South East Chequer South Cardinal Float.
- 2) Depths of between 8.2 metres below Chart Datum and 10.7 metres below Chart Datum have encroached up to 790 metres into the Southern buoy-line of the Inward Traffic Separation Scheme lane, from the Alpha Buoy to 1500 metres East North East of the Bravo Buoy.

MARINERS ARE ADVISED to navigate with caution in this area and Notice to Mariners No. H. 138/2019 is hereby cancelled.

**CAPT. A. FIRMAN
HARBOUR MASTER, HUMBER**

10th September 2021

THE INTERNET

In order to widen communication between ABP Humber Estuary Services and those with an interest in the estuary, you are invited to visit our website which carries a wide range of information, including current live weather and Buoy positions, charts, tidal information and copies of this and other Notice to Mariners.
www.humber.com