

NOTICE TO MARINERS

No. H. 135/2022

RIVER HUMBER

HESSLE SAND - SHOAL WATER

MARINERS ARE WARNED that a survey carried out on the 15th September 2022 shows the following: -

- 1) A least depth of 0.4 metres below Chart Datum exists close South of the ships course from 180 metres to 800 metres upstream of the No. 28 Light Buoy.

Deeper water exists on and to the North of the ships course in this vicinity.

- 2) A least depth of 0.3 metres **ABOVE** Chart Datum exists North of the ships course 640 metres upstream of the No. 23 Light Float.

Deeper water exists on and to the South of the ships course in this vicinity.

MARINERS ARE ADVISED that 0 metres at Chart Datum should be used for passage planning purposes and Notices to Mariners H. 95/2022 is hereby cancelled.

**CAPT. A FIRMAN
HARBOUR MASTER, HUMBER**

15th September 2022

THE INTERNET

In order to widen communication between ABP Humber Estuary Services and those with an interest in the estuary, you are invited to visit our website which carries a wide range of information, including current live weather and Buoy positions, charts, tidal information and copies of this and other Notice to Mariners.

www.humber.com