
NOTICE TO MARINERS

No. H. 15/2023

RIVER HUMBER

GRIMSBY MIDDLE - SHOAL WATER

MARINERS ARE WARNED that surveys carried out on the 6th and 7th February 2023 show the following: -

- 1) Depths of less than 6.4 metres below Chart Datum have encroached up to 30 metres into the Northern edge of the navigation channel from 80 metres downstream to 275 metres upstream of the No. 5A Light Buoy.

Deeper water exists to the South in this vicinity.

- 2) Depths of less than 6.4 metres below Chart Datum have encroached up to 50 metres into the Southern edge of the navigation channel from 575 metres upstream of the No. 4A Clee Ness Light Float to 400 metres downstream of the No. 4B Light Buoy.

Deeper water exists to the North in this vicinity.

- 3) Depths of less than 6.4 metres below Chart Datum have encroached up to 50 metres into the Southern edge of the navigation channel from 380 metres to 620 metres downstream of the No. 8 Middle Burcom Light Buoy.

Deeper water exists to the North in this vicinity.

MARINERS ARE ADVISED that Notice to Mariners No. H. 120/2022 is hereby cancelled.

CAPT. A. FIRMAN
HARBOUR MASTER, HUMBER

8th February 2023

THE INTERNET

In order to widen communication between ABP Humber Estuary Services and those with an interest in the estuary, you are invited to visit our website which carries a wide range of information, including current live weather and Buoy positions, charts, tidal information and copies of this and other Notice to Mariners.

www.humber.com