
NOTICE TO MARINERS

No. H. 150/2022

HUMBER APPROACHES

HUMBER LIGHT FLOAT RE-DEPLOYMENT

MARINERS ARE ADVISED that following routine maintenance, the Humber Light Float has been re-deployed to its original charted position.

The Green mono-hull Light Float exhibits the following characteristics:

Latitude: 53° 38.700' N Longitude: 0° 21.240' E (WGS 84)

Characteristics: LFI.G.10s

Racon: (T)

AIS name: Humber Light Float

MMSI: 992351174

MARINERS ARE ADVISED that Notice to Mariners No. H.178/2021 is hereby cancelled.

**CAPT. A. FIRMAN
HARBOUR MASTER, HUMBER**

11th October 2022

LOCAL NOTICE TO MARINERS FOR 2019, 2020, 2021 & 2022 CURRENTLY IN FORCE:

H. 27/2019, H. 43/2020, H. 68/2020, H. 160/2020, H. 02/2021, H. 07/2021, H. 24/2021, H. 43/2021, H. 64/2021, H. 92/2021, H. 109/2021, H. 179/2021, H. 08/2022, H. 19/2022, H. 28/2022, H. 37/2022, H. 54/2022, H. 68/2022, H. 75/2022, H. 90/2022, H. 104/2022, H. 111/2022, H. 115/2022, H. 118/2022, H. 120/2022, H. 121/2022, H. 126/2022, H. 127/2022, H. 128/2022, H. 130/2022, H. 131/2022, H. 135/2022, H. 136/2022, H. 138/2022, H. 140/2022, H. 143/2022, H. 144/2022, H. 145/2022, H. 146/2022, H. 147/2022, H. 148/2022, H. 149/2022, H. 150/2022.

THE INTERNET

In order to widen communication between ABP Humber Estuary Services and those with an interest in the estuary, you are invited to visit our website which carries a wide range of information, including current live weather and Buoy positions, charts, tidal information and copies of this and other Notice to Mariners.

www.humber.com