
NOTICE TO MARINERS

No. H. 176/2021

U P P E R H U M B E R

REVISED MOVES OF FLOATING MARKS AND SHOAL WATER

MARINERS ARE ADVISED that due to unforeseen circumstances, only two of the floating mark moves advertised in Notice to Mariners No. H. 175/2021 have been successfully carried out.

Whilst the Cappers West and Middle Whitton Light Floats are now in their new positions (detailed below), the No. 33 Light Buoy remains in its original charted position: -

1) Cappers West Light Float:

Latitude 53° 41.749' N, Longitude 0° 33.588' W (WGS 84)

2) No. 33 Light Buoy:

Latitude 53° 42.185' N, Longitude 0° 34.465' W (WGS 84)

3) Middle Whitton Light Float:

Latitude 53° 42.400' N, Longitude 0° 34.944' W (WGS 84)

MARINERS ARE WARNED that the following shoal water now exists: -

1) A least depth of 1.1 metres **ABOVE** Chart Datum exists North of the ships course 210 metres downstream of the Lower Whitton Light Float.

Deeper water exists on the ships course in this vicinity.

2) A least depth of 0.3 metres below Chart Datum exists North of the ships course 235 metres upstream of the Lower Whitton Light Float.

Deeper water exists on the ships course in this vicinity.

3) A least depth of 0 metres at Chart Datum exists North of the ships course 375 metres downstream of the No. 33 Light Float.

Deeper water exists on and to the South of the ships course in this vicinity.

- 4) A least depth of 0.1 metres **ABOVE** Chart Datum exists South of the ships course 455 metres upstream of the Middle Whiton Light Float.

Deeper water exists on and to the North of the ships course in this vicinity.

MARINERS ARE ADVISED that 0.2 metres below Chart Datum should be used for passage planning purposes and Notice to Mariners No. H. 175/2021 is hereby cancelled.

**CAPT. A. FIRMAN
HARBOUR MASTER, HUMBER**

10th December 2021

THE INTERNET

In order to widen communication between ABP Humber Estuary Services and those with an interest in the estuary, you are invited to visit our website which carries a wide range of information, including current live weather and Buoy positions, charts, tidal information and copies of this and other Notice to Mariners.
www.humber.com