

NOTICE TO MARINERS

No. H. 21/2025

RIVER HUMBER

FOUL HOLME CHANNEL - SHOAL WATER

MARINERS ARE WARNED that a survey carried out on the 10th February 2025 shows the following: -

- 1) A least depth of 2.0 metres below Chart Datum exists on the Eastern edge of the channel from 75 metres to 175 metres upstream of the FH3 Light Buoy.

Deeper water exists to the West in this vicinity.

- 2) Depths of between 1.8 metres and 2.0 metres below Chart Datum have encroached up to 20 metres into the Eastern edge of the channel from 30 metres downstream of the FH7 Light Buoy to 440 metres downstream of the FH9 Light Buoy.

Deeper water exists to the West in this vicinity.

MARINERS ARE ADVISED that 1.5 metres below Chart Datum should be used for passage planning purposes and Notice to Mariners No. H. 128/2024 is hereby cancelled.

**CAPT. A. FIRMAN
HARBOUR MASTER, HUMBER**

11th February 2025

THE INTERNET

In order to widen communication between ABP Humber Estuary Services and those with an interest in the estuary, you are invited to visit our website which carries a wide range of information, including current live weather and Buoy positions, charts, tidal information and copies of this and other Notice to Mariners.

www.humber.com