

---

# NOTICE TO MARINERS

---

No. H. 22/2022

## RIVER TRENT

### DISCONTINUATION OF AIDS TO NAVIGATION

**MARINERS ARE REMINDED** that the following navigation lights on the Lower Trent have been discontinued:

- 1) Island House
  - Position – Lat. 53° 40.625'N, Long. 0° 41.386'W
  - Light Characteristic – Lighted Beacon FI G 2s
- 2) West Trent
  - Position – Lat. 53° 40.831'N, Long 0° 41.734'W.
  - Characteristics – Lighted Beacon Q G
- 3) Henderson
  - Position – Lat. 53° 41.010'N, Long 0° 41.870'W
  - Characteristics – Lighted Beacon Iso G 4s
- 4) Adlingfleet Drain
  - Position – Lat. 53° 41.196'N, Long 0° 41.994'W
  - Characteristics – Lighted Beacon FI G 2s

**MARINERS ARE ADVISED** that although unlit, the structures remain in the charted positions as above.

**CAPT. A. FIRMAN.**  
**HARBOUR MASTER, HUMBER**

17<sup>th</sup> February 2022

THE INTERNET

In order to widen communication between ABP Humber Estuary Services and those with an interest in the estuary, you are invited to visit our website which carries a wide range of information, including current live weather and Buoy positions, charts, tidal information and copies of this and other Notice to Mariners.

[www.humber.com](http://www.humber.com)