

NOTICE TO MARINERS

No. H. 42/2024

UPPER HUMBER

SHOAL WATER

MARINERS ARE WARNED that surveys carried out on the 26th to 27th March and 9th April 2024 show the following: -

- 1) A least depth of 2.3 metres **ABOVE** Chart Datum exists North of the ships course 315 metres downstream of the Lower Whitton Light Float.
 - Deeper water exists on the ships course in this vicinity.
- 2) A least depth of 0.3 metres **ABOVE** Chart Datum exists North of the ships course 540 metres downstream of the No. 31 Light Float.
 - Deeper water exists on and to the South of the ships course in this vicinity.
- 3) A least depth of 0.1 metres **ABOVE** Chart Datum exists North of the ships course from 250 metres downstream of the No. 32C Light Buoy.
 - Deeper water exists on the ships course in this vicinity.
- 4) A least depth of 0.3 <u>ABOVE</u> metres at Chart Datum exists North of the ships course 610 metres downstream of the No.34 Light Buoy.

Deeper water exists on the ships course in this vicinity.

MARINERS ARE ADVISED that 0 metres at Chart Datum should be used for passage planning purposes and Notice to Mariners No. H. 39/2024 is hereby cancelled.

CAPT. A. FIRMAN HARBOUR MASTER, HUMBER

9th April 2024

THE INTERNET

In order to widen communication between ABP Humber Estuary Services and those with an interest in the estuary, you are invited to visit our website which carries a wide range of information, including current live weather and Buoy positions, charts, tidal information and copies of this and other Notice to Mariners.