

---

# NOTICE TO MARINERS

---

No. H. 50/2022

## U P P E R H U M B E R

### DISCONTINUATION OF AID TO NAVIGATION

**NOTICE IS HEREBY GIVEN** that with immediate effect the following navigation mark has been permanently discontinued:

Broomfleet East

- Position – Lat. 53° 43.427' N, Long. 0° 39.634' W
- Characteristic – Conical G

**CAPT. A. FIRMAN.**  
**HARBOUR MASTER, HUMBER**

19<sup>th</sup> February 2022

**LOCAL NOTICE TO MARINERS FOR 2019, 2020, 2021 & 2022 CURRENTLY IN FORCE:**

H. 27/2019, H. 39/2020, H. 40/2020, H. 43/2020, H. 67/2020, H. 68/2020, H. 160/2020, H. 02/2021, H. 07/2021, H. 24/2021, H. 43/2021, H. 64/2021,  
H. 92/2021, H. 109/2021, H. 133/2021, H. 178/2021, H. 179/2021, H. 06/2022, H. 08/2022, H. 10/2022, H. 12/2022,  
H. 16/2022, H. 18/2022, H. 19/2022, H. 20/2022, H. 22/2022, H. 27/2022, H. 28/2022, H. 30/2022, H. 36/2022, H. 37/2022,  
H. 38/2022, H. 41/2022, H. 43/2022, H. 44/2022, H. 46/2022,  
H. 48/2022, H. 49/2022, H. 50/2022.

**THE INTERNET**

In order to widen communication between ABP Humber Estuary Services and those with an interest in the estuary, you are invited to visit our website which carries a wide range of information, including current live weather and Buoy positions, charts, tidal information and copies of this and other Notice to Mariners.

[www.humber.com](http://www.humber.com)