

NOTICE TO MARINERS

No. H. 94/2022

UPPER HUMBER

SHOAL WATER

MARINERS ARE WARNED that surveys carried out on the 16th and 21st June 2022 show the following: -

- 1) A least depth of 1.9 metres **ABOVE** Chart Datum exists North of the ships course 180 metres downstream of the Lower Whitton Light Float.

Deeper water exists on the ships course in this vicinity.

- 2) A least depth of 0.4 metres below Chart Datum exists South of the ships course 85 metres upstream of the No. 33 Light Float.

Deeper water exists on the ships course in this vicinity.

- 3) A least depth of 0.2 metres **ABOVE** Chart Datum exists South of the ships course from 200 to 360 metres downstream of the Upper Whitton Light Float.

Deeper water exists on and to the North of the ships course in this vicinity.

MARINERS ARE ADVISED that 0.2 metres below Chart Datum should be used for passage planning purposes and Notice to Mariners No. H. 92/2022 is hereby cancelled.

**CAPT. A. FIRMAN
HARBOUR MASTER, HUMBER**

22nd June 2022

THE INTERNET

In order to widen communication between ABP Humber Estuary Services and those with an interest in the estuary, you are invited to visit our website which carries a wide range of information, including current live weather and Buoy positions, charts, tidal information and copies of this and other Notice to Mariners.

www.humber.com