
NOTICE TO MARINERS

No. H. 08/2026

RIVER HUMBER

HALTON MIDDLE - SHOAL WATER

MARINERS ARE WARNED that surveys carried out on the 18th December 2025 and the 14th January 2026 show the following: -

- 1) A least depth of 5.5 metres below Chart Datum exists up to 84 metres into the Eastern edge of the channel 760 metres downstream of the No. 15A Light Buoy.

Deeper water exists to the West in this vicinity.

- 2) Depths of between 5.4 metres and 5.5 metres below Chart Datum have encroached up to 30 metres into the Eastern edge of the channel from 231 metres downstream to 300 metres downstream of the No. 15A Light Buoy.

Deeper water exists to the West in this vicinity.

- 3) Depths of between 4.4 metres and 5.5 metres below Chart Datum have encroached up to 70 metres into the Western edge of the channel from 895 metres downstream to 600 metres upstream of the No. 14 Skitter Haven Light Buoy.

Deeper water exists to the East in this vicinity.

MARINERS ARE ADVISED that 5.4 metres below Chart Datum should be used for passage planning purposes and Notice to Mariners No. H. 179/2025 is hereby cancelled.

CAPT. A. FIRMAN
HARBOUR MASTER, HUMBER

15th January 2026

THE INTERNET

In order to widen communication between ABP Humber Estuary Services and those with an interest in the estuary, you are invited to visit our website which carries a wide range of information, including current live weather and Buoy positions, charts, tidal information and copies of this and other Notice to Mariners.

www.humber.com