
NOTICE TO MARINERS

No. H. 12/2026

U P P E R H U M B E R

SHOAL WATER

MARINERS ARE WARNED that surveys carried out on the 20th and 21st January 2026 show the following:

- 1) A least depth of 0.6 metres **ABOVE** Chart Datum exists close North of the ships course 260 metres downstream of the Lower Whitton Light Float.

Deeper water exists on and to the South of the ships course in this vicinity.

- 2) Depths of between 0 metres at Chart Datum and 0.3 metres **ABOVE** Chart Datum exist North of the ships course from 200 metres downstream to 125 metres upstream of the No. 31 Light Float.

Deeper water exists on the ships course in this vicinity.

- 3) Depths of between 0 metres at Chart Datum and 0.4 metres **ABOVE** Chart Datum exist South of the ships course from the No. 33 Light Float to 220 metres downstream of the No. 32B Light Float.

Deeper water exists on the ships course in this vicinity.

- 4) A least depth of 0.1 metres **ABOVE** Chart Datum exists North of the ships course 460 metres upstream of the No. 32C Light Buoy.

Deeper water exists on and to the South of the ships course in this vicinity.

MARINERS ARE ADVISED that 0 metres at Chart Datum should be used for passage planning purposes and that Notice to Mariners No. H. 10/2026 is hereby cancelled.

CAPT. A. FIRMAN
HARBOUR MASTER, HUMBER

21st January 2026

THE INTERNET

In order to widen communication between ABP Humber Estuary Services and those with an interest in the estuary, you are invited to visit our website which carries a wide range of information, including current live weather and Buoy positions, charts, tidal information and copies of this and other Notice to Mariners.
www.humber.com