
NOTICE TO MARINERS

No. H.33/2026

RIVER HUMBER

BULL CHANNEL - SHOAL WATER

MARINERS ARE WARNED that surveys carried out on the 2nd and 3rd of March show the following: -

- 1) Depths of between 4.1 metres and 5.5 metres below Chart Datum have encroached up to 460 metres into the Southern edge of the channel, from 1075 metres upstream of the Bull Light Float (North Cardinal) to 440 metres downstream of the Bull Sand Light Buoy.

Deeper water exists to the North in this vicinity.

- 2) A shoal with depths of between 4.1 metres and 5.5 metres below Chart Datum extends from 1065 metres upstream of the Bull Light Float (North Cardinal) to 200 metres upstream of the Bull Sand Light Buoy.

- 3) Depths of between 5.2 metres and 5.5 metres below Chart Datum have encroached up to 100 metres into the Northern edge of the channel, from 885 metres to 470 metres downstream of the No. 5A Light Buoy.

Deeper water exists to the South in this vicinity.

MARINERS ARE ADVISED that Notice to Mariners No. H. 147/2025 is hereby cancelled.

**CAPT. A. FIRMAN.
HARBOUR MASTER, HUMBER**

4th March 2026

THE INTERNET

In order to widen communication between ABP Humber Estuary Services and those with an interest in the estuary, you are invited to visit our website which carries a wide range of information, including current live weather and Buoy positions, charts, tidal information and copies of this and other Notice to Mariners.

www.humber.com