
NOTICE TO MARINERS

No. H. 114/2015

RIVER HUMBER

IMMINGHAM – DISCONTINUATION OF TRAFFIC SIGNALS

NOTICE IS HEREBY GIVEN that with immediate effect the following navigation lights have been permanently discontinued:

Sailing Lights Immingham

- Tower A – Immingham Dock Entrance - N06311
 - Position – Lat. 53° 37.809' N, 000° 11.259' W
 - Light Characteristic – Array Fl 2s
- Tower B – Immingham Oil Terminal - N06312
 - Position – Lat. 53° 37.760' N, 000° 09.865' W
 - Characteristic of signal as for Tower 'A' exhibited synchronously

MARINERS ARE ADVISED that Notice to Mariners No.H.121/2013 is hereby cancelled.

**CAPT. A. FIRMAN.
HARBOUR MASTER, HUMBER**

19 October 2015

THE INTERNET

In order to widen communication between ABP Humber Estuary Services and those with an interest in the estuary, you are invited to visit our website which carries a wide range of information, including current live weather and Buoy positions, charts, tidal information and copies of this and other Notice to Mariners.

www.humber.com