
NOTICE TO MARINERS

No. H. 134/2017

RIVER OUSE

SHOAL WATER

MARINERS ARE WARNED that surveys carried out between the 29th September and the 6th October 2017 show the following: -

- 1) A least depth of 1.0 metres **ABOVE** Chart Datum exists 250 metres from the North bank 80 metres upstream of Apex Light.

Deeper water exists to the South in this vicinity.

- 2) A least depth of 0.6 metres below Chart Datum exists 245 metres from the North bank 140 metres downstream of No. 2 Boundary Light.

Deeper water exists to the South in this vicinity.

**CAPT. A FIRMAN
HARBOUR MASTER, HUMBER**

17th October 2017

THE INTERNET

In order to widen communication between ABP Humber Estuary Services and those with an interest in the estuary, you are invited to visit our website which carries a wide range of information, including current live weather and Buoy positions, charts, tidal information and copies of this and other Notice to Mariners.

www.humber.com