
NOTICE TO MARINERS

No. H. 197/2018

RIVER HUMBER

HALTON MIDDLE - SHOAL WATER

MARINERS ARE WARNED that a survey carried out on the 19th December 2018 show the following: -

- 1) Depths of between 3.9 metres and 5.5 metres below Chart Datum have encroached up to 320 metres into the East side of the channel from 620 metres downstream of the No. 15A Light Buoy to 240 metres downstream of the No. 17 North Holme Light Float.

Deeper water exists to the West in this vicinity.

- 2) Depths of between 5.1 metres and 5.5 metres below Chart Datum have encroached up to 290 metres into the West side of the channel from 1470 metres to 1035 metres upstream of the No. 12 Killingholme Light Buoy.

Deeper water exists to the East in this vicinity.

- 3) Depths of between 5.1 metres and 5.5 metres below Chart Datum have encroached up to 45 metres into the West side of the channel from 420 metres downstream to 440 metres upstream of the No. 14 Skitter Haven Light Buoy.

Deeper water exists to the East in this vicinity.

MARINERS ARE ADVISED that 5.1 metres below Chart Datum should be used for passage planning and Notice to Mariners No. H. 167/2018 is hereby cancelled.

**CAPT. A. FIRMAN
HARBOUR MASTER, HUMBER**

21st December 2018

THE INTERNET

In order to widen communication between ABP Humber Estuary Services and those with an interest in the estuary, you are invited to visit our website which carries a wide range of information, including current live weather and Buoy positions, charts, tidal information and copies of this and other Notice to Mariners.
www.humber.com