
NOTICE TO MARINERS

No. H.06/2017

RIVER HUMBER

BULL SAND - SHOAL WATER

MARINERS ARE WARNED that a survey carried out on the 12th January 2017 shows the following:-

Depths of between 4.2 metres and 5.5 metres below Chart Datum have encroached up to 450 metres into the southern edge of the channel from 1020 metres upstream to 350 metres downstream of the North Fort Cardinal Buoy.

Deeper water exists to the North in this vicinity.

MARINERS ARE ADVISED that Notice to Mariners No. H. 131/2016 is hereby cancelled.

**CAPT. A. FIRMAN.
HARBOUR MASTER, HUMBER**

13th January 2017

THE INTERNET

In order to widen communication between ABP Humber Estuary Services and those with an interest in the estuary, you are invited to visit our website which carries a wide range of information, including current live weather and Buoy positions, charts, tidal information and copies of this and other Notice to Mariners.

www.humber.com