
NOTICE TO MARINERS

No. H. 107/2017

RIVER HUMBER

HALTON MIDDLE - SHOAL WATER

MARINERS ARE WARNED that surveys carried out on the 17th and 18th August 2017 show the following: -

- 1) Depths of between 5.4 metres and 5.5 metres below Chart Datum have encroached up to 190 metres into the East side of the channel, from 420 metres to 730 metres downstream of the No. 15A Light Buoy.

Deeper water exists to the West in this vicinity.

- 2) Depths of between 5.3 metres and 5.5 metres below Chart Datum have encroached up to 20 metres into the East side of the channel 630 metres upstream of the No. 15A Light Buoy.

Deeper water exists to the West in this vicinity.

- 3) Depths of between 4.3 metres and 5.5 metres below Chart Datum have encroached up to 140 metres into the West side of the channel from the No 12 Killingholme Light Buoy to 995 metres upstream of the No. 14 Skitter Haven Light Buoy.

Deeper water exists to the East in this vicinity.

MARINERS ARE ADVISED that Notice to Mariners No. H. 64/2017 is hereby cancelled.

**CAPT. A. FIRMAN
HARBOUR MASTER, HUMBER**

18th August 2017

THE INTERNET

In order to widen communication between ABP Humber Estuary Services and those with an interest in the estuary, you are invited to visit our website which carries a wide range of information, including current live weather and Buoy positions, charts, tidal information and copies of this and other Notice to Mariners.
www.humber.com