

---

# **NOTICE TO MARINERS**

---

**No. H.120/2017**

## **RIVER HUMBER**

### **BULL SAND - SHOAL WATER**

**MARINERS ARE WARNED** that a survey carried out on the 18<sup>th</sup> September 2017 shows the following:-

Depths of between 4.0 metres and 5.5 metres below Chart Datum have encroached up to 600 metres into the southern edge of the channel from 960 metres upstream to 610 metres downstream of the North Fort Cardinal Buoy.

Deeper water exists to the North in this vicinity.

**MARINERS ARE ADVISED** that Notice to Mariners No. H. 80/2017 is hereby cancelled.

**CAPT. A. FIRMAN.  
HARBOUR MASTER, HUMBER**

20<sup>th</sup> September 2017

**LOCAL NOTICE TO MARINERS FOR 2012, 2014, 2015, 2016 & 2017 CURRENTLY IN FORCE:**

H. 15/2012, H. 50/2014, H. 42/2015, H. 78/2015, H. 110/2015, H. 61/2016, H. 114/2016, H. 161/2016, H. 02/2017, H. 09/2017, H. 11/2017, H. 22/2017, **H. 24/2017**, H. 31/2017, **H. 34/2017**, **H. 41/2017**, H. 44/2017, H. 50/2017, H. 55/2017, H. 59/2017, **H. 62/2017**, **H. 74/2017**, **H. 82/2017**, **H. 83/2017**, **H. 92/2017**, H. 94/2017, H. 95/2017, H. 96/2017, **H. 99/2017**, H.100/2017, **H.102/2017**, H. 103/2017, H. 104/2017, H. 105/2017, H. 107/2017, H. 108/2017, H. 109/2017, H. 110/2017, H. 114/2017, **H. 118/2017**, H. 119/2017, H. 120/2017

**THE INTERNET**

In order to widen communication between ABP Humber Estuary Services and those with an interest in the estuary, you are invited to visit our website which carries a wide range of information, including current live weather and Buoy positions, charts, tidal information and copies of this and other Notice to Mariners.

[www.humber.com](http://www.humber.com)