

---

# NOTICE TO MARINERS

---

No. H. 123/2018

## RIVER HUMBER

### HESSLE SAND - SHOAL WATER

**MARINERS ARE WARNED** that a survey carried out on the 1<sup>st</sup> August 2018 shows the following: -

A least depth of 0.8 metres **ABOVE** Chart Datum exists close North of the ships course 280 metres upstream of the No. 23 Light Buoy.

Deeper water exists to the South of the ships course in this vicinity.

**MARINERS ARE ADVISED** that 0.8 metres **ABOVE** Chart Datum should be used for passage planning and Notice to Mariners No. H. 102/2018 hereby cancelled.

**CAPT. A FIRMAN  
HARBOUR MASTER, HUMBER**

1<sup>st</sup> August 2018

THE INTERNET

In order to widen communication between ABP Humber Estuary Services and those with an interest in the estuary, you are invited to visit our website which carries a wide range of information, including current live weather and Buoy positions, charts, tidal information and copies of this and other Notice to Mariners.

[www.humber.com](http://www.humber.com)