
NOTICE TO MARINERS

No. H. 129/2017

RIVER HUMBER

HESSLE SAND – SHOAL WATER

MARINERS ARE WARNED that a survey carried out on the 28th September 2017 shows the following:

- 1) A least depth of 0.2 metres below Chart Datum exists in the navigable channel from 440 metres upstream to 400 metres downstream of the No. 23 Light Buoy.
- 2) A least depth of 0.2 metres **ABOVE** Chart Datum exists close North of the ships course 550 metres upstream of the No. 23 Light Buoy.

Deeper water exists on and to the South of the ships course in this vicinity.

MARINERS ARE ADVISED that 0.1 metres **ABOVE** Chart Datum should be used for passage planning purposes and that Notice to Mariners No. H.104/2017 is hereby cancelled.

**CAPT. A FIRMAN
HARBOUR MASTER, HUMBER**

29th September 2017

THE INTERNET

In order to widen communication between ABP Humber Estuary Services and those with an interest in the estuary, you are invited to visit our website which carries a wide range of information, including current live weather and Buoy positions, charts, tidal information and copies of this and other Notice to Mariners.

www.humber.com