
NOTICE TO MARINERS

No. H. 132/2017

U P P E R H U M B E R

SHOAL WATER

MARINERS ARE WARNED that a survey carried out on the 9th October 2017 shows the following: -

- 1) A least depth of 0.6 metres **ABOVE** Chart Datum exists close North of the ships course 335 metres downstream of the Lower Whitton Light Float.

Deeper water exists on and to the South of the ships course in this vicinity.

- 2) A least depth of 0.4 metres below Chart Datum exists close North of the ships course in the vicinity of the No.33A Light Float.

Deeper water exists on and to the South of the ships course in this vicinity.

- 3) A least depth of 0.5 metres below Chart Datum exists in the navigable channel from 410 metres downstream to 660 metres upstream of the No 33A Light Float.

- 4) A least depth of 0 metres at Chart Datum exists North of the ships course 835 metres upstream of the Upper Whitton Light Float.

Deeper water exists on the ships course in this vicinity.

- 5) A least depth of 0.1 metres **ABOVE** Chart Datum exists South of the ships course 315 metres downstream of the No. 32C Light Buoy.

Deeper water exists on the ships course in this vicinity.

- 6) A least depth of 0.1 metres **ABOVE** at Chart Datum exists North of the ships course 380 metres downstream of the No. 34 Light Buoy.

Deeper water exists on and to the South of the ships course in this vicinity.

- 7) A least depth of 0.2 metres below Chart Datum exists close North of the ships course 190 metres downstream of the No. 34 Light Buoy.

Deeper water exists on the ships course in this vicinity.

MARINERS ARE ADVISED that 0.1 metres below Chart Datum should be used for passage planning purposes and that Notice to Mariners No. H. 124/2017 is hereby cancelled.

CAPT. A. FIRMAN
HARBOUR MASTER, HUMBER
9th October 2017

THE INTERNET

In order to widen communication between ABP Humber Estuary Services and those with an interest in the estuary, you are invited to visit our website which carries a wide range of information, including current live weather and Buoy positions, charts, tidal information and copies of this and other Notice to Mariners.

www.humber.com