
NOTICE TO MARINERS

No. H. 149/2018

HUMBER APPROACHES

TEMPORARY SPURN LIGHT FLOAT – RETURNED TO STATION

NOTICE IS HEREBY GIVEN that the Spurn Light Float has been returned to station in its original charted position as follows:

Latitude: 53° 33.417' N Longitude: 0° 14.148' E

Characteristics: Q(3)10s

MARINERS ARE FURTHER ADVISED Notice to Mariners No. H. 145/2018 is hereby cancelled.

**CAPT. A. FIRMAN
HARBOUR MASTER, HUMBER**

13 September 2018

THE INTERNET

In order to widen communication between ABP Humber Estuary Services and those with an interest in the estuary, you are invited to visit our website which carries a wide range of information, including current live weather and Buoy positions, charts, tidal information and copies of this and other Notice to Mariners.