
NOTICE TO MARINERS

No. H. 156/2018

RIVER HUMBER

HULL ROADS – WEST MIDDLE – SHOAL WATER

MARINERS ARE WARNED that a survey carried out on the 1st October 2018 shows the following: -

- 1) A least depth of 4.0 metres below Chart Datum exists on the Southern edge of the channel from 55 metres upstream to 525 metres downstream of the No. 26 Upper West Middle Light Buoy.

Deeper water exists to the North in this vicinity.

- 2) Depths of between 4.0 metres and 5.5 metres below Chart Datum have encroached up to 165 metres into the Southern edge of the channel from 262 metres upstream of the No. 24 Lower West Middle Light Buoy to 80 metres downstream of the No. 26A Light Buoy.

Deeper water exists to the North in this vicinity.

MARINERS ARE ADVISED that Notice to Mariners No. H. 121/2018 is hereby cancelled.

**CAPT. A FIRMAN
HARBOUR MASTER, HUMBER**

1st October 2018

THE INTERNET

In order to widen communication between ABP Humber Estuary Services and those with an interest in the estuary, you are invited to visit our website which carries a wide range of information, including current live weather and Buoy positions, charts, tidal information and copies of this and other Notice to Mariners.

www.humber.com