
NOTICE TO MARINERS

No. H. 167/2018

RIVER HUMBER

HALTON MIDDLE - SHOAL WATER

MARINERS ARE WARNED that surveys carried out on the 22nd and 23rd October 2018 show the following: -

- 1) Depths of between 4.1 metres and 5.5 metres below Chart Datum have encroached up to 270 metres into the East side of the channel from 400 metres downstream of the No. 15A Light Buoy to 410 metres downstream of the No. 17 North Holme Light Float.

Deeper water exists to the West in this vicinity.

- 2) Depths of 5.5 metres below Chart Datum have encroached up to 280 metres into the West side of the channel from 1580 metres to 1495 metres upstream of the No. 12 Killingholme Light Buoy.

Deeper water exists to the East in this vicinity.

- 3) Depths of between 5.0 metres and 5.5 metres below Chart Datum have encroached up to 50 metres into the West side of the channel from 380 metres downstream to 410 metres upstream of the No. 14 Skitter Haven Light Buoy.

Deeper water exists to the East in this vicinity.

MARINERS ARE ADVISED that Notice to Mariners No. H. 106/2018 is hereby cancelled.

**CAPT. A. FIRMAN
HARBOUR MASTER, HUMBER**

24th October 2018

THE INTERNET

In order to widen communication between ABP Humber Estuary Services and those with an interest in the estuary, you are invited to visit our website which carries a wide range of information, including current live weather and Buoy positions, charts, tidal information and copies of this and other Notice to Mariners.

www.humber.com