

NOTICE TO MARINERS

No. H. 173/2018

RIVER HUMBER

FOUL HOLME CHANNEL - SHOAL WATER

MARINERS ARE WARNED that a survey carried out on the 2nd November 2018 shows the following:-

Depths of between 0 metres at Chart Datum and 0.4 metres **ABOVE** Chart Datum have encroached up to 60 metres into the Eastern edge of the channel from 800 metres upstream of the FH3 Light Buoy to 460 metres downstream of the FH5 Light Buoy.

Deeper water exists to the West in this vicinity.

MARINERS ARE ADVISED that 0.4 metres **ABOVE** Chart Datum should be used for passage planning purposes and Notice to Mariners No. H. 124/2018 is hereby cancelled.

CAPT. A. FIRMAN
HARBOUR MASTER, HUMBER

5th November 2018

THE INTERNET

In order to widen communication between ABP Humber Estuary Services and those with an interest in the estuary, you are invited to visit our website which carries a wide range of information, including current live weather and Buoy positions, charts, tidal information and copies of this and other Notice to Mariners.

www.humber.com