
NOTICE TO MARINERS

No. H. 18/2019

HUMBER APPROACHES

ESTABLISHMENT OF TEMPORARY HUMBER LIGHT FLOAT

NOTICE IS HEREBY GIVEN that the Humber Light Float has been replaced with a temporary mono-hull light float with the following characteristics:

Latitude: 53° 38.700' N Longitude: 0° 21.240' E

Characteristics: LFI.G.10s

NO RACON

AIS name: Humber Light Float

MMSI: 992351174

MARINERS ARE ADVISED that Notice to Mariners No. H.16/2019 is hereby cancelled.

**CAPT. A. FIRMAN
HARBOUR MASTER, HUMBER**

06th February 2019

THE INTERNET

In order to widen communication between ABP Humber Estuary Services and those with an interest in the estuary, you are invited to visit our website which carries a wide range of information, including current live weather and Buoy positions, charts, tidal information and copies of this and other Notice to Mariners.

www.humber.com