
NOTICE TO MARINERS

No. H.186/2018

RIVER HUMBER

BULL SAND - SHOAL WATER

MARINERS ARE WARNED that a survey carried out on the 23rd November 2018 shows the following:-

Depths of between 3.0 metres and 5.5 metres below Chart Datum have encroached up to 655 metres into the southern edge of the channel from 650 metres downstream to 1000 metres upstream of the North Fort Cardinal Buoy.

Deeper water exists to the North in this vicinity.

MARINERS ARE ADVISED that Notice to Mariners No. H. 125/2018 is hereby cancelled.

**CAPT. A. FIRMAN.
HARBOUR MASTER, HUMBER**

26th November 2018

THE INTERNET

In order to widen communication between ABP Humber Estuary Services and those with an interest in the estuary, you are invited to visit our website which carries a wide range of information, including current live weather and Buoy positions, charts, tidal information and copies of this and other Notice to Mariners.

www.humber.com