
NOTICE TO MARINERS

No. H. 24/2017

R I V E R H U M B E R

HESSLE SAND - MOVES OF FLOATING MARKS AND SHOAL WATER

NOTICE IS HEREBY GIVEN that it is proposed on Tuesday 28th February 2017 (or as soon after as circumstances permit) to move in order: -

1) The No. 27 Light Float to a position:

Latitude 53° 42.534' N, Longitude 0° 26.294' W (WGS 84)

(1773 metres West of its current position).

2) The No. 28A Light Float to a position:

Latitude 53° 42.345' N, Longitude 0° 24.591' W (WGS 84)

(1719 metres East of its current position).

3) The No. 23 Light Buoy to a position:

Latitude 53° 43.028' N, Longitude 0° 23.681 W (WGS 84)

(1225 metres West of its current position).

On completion of the above moves, the new North channel will be open to traffic.

4) The No. 28 Light Buoy to a position:

Latitude 53° 43.369' N, Longitude 0° 22.394' W (WGS 84)

(548 metres West South West of its current position).

MARINERS ARE ADVISED that on completion of the above moves the order of the red No. 28A Light Float and green No. 27 Light Float will be reversed. The North

channel and Skitter Channel will then converge at the new position of the No. 28A Light Float.

The new order of buoyage when navigating upstream via the Skitter Channel will be as follows:

No. 22A Light Buoy
No. 28A Light Float (new position)
No. 27 Light Float (new position)
No. 29 Light Float

The new order of buoyage when navigating upstream via the North Channel will be as follows:

No. 26A Light Buoy
No. 28 Light Buoy (new position)
No. 23 Light Buoy (new position)
No. 28A Light Float (new position)
No. 27 Light Float (new position)
No. 29 Light Float

MARINERS ARE WARNED that on completion of the above moves the following shoal water will exist: -

A least depth of 0.2 metres below Chart Datum on the ships course 475 metres upstream of the No. 23 Light Buoy.

Deeper water exists to the North of the ships course in this vicinity.

MARINERS ARE FURTHER ADVISED that on completion of the above moves 0.2 metres below Chart Datum should be used for passage planning purposes and Notice to Mariners No. H. 20/2017 will be cancelled.

**CAPT. A. FIRMAN
HARBOUR MASTER, HUMBER**

23rd February 2017

THE INTERNET

In order to widen communication between ABP Humber Estuary Services and those with an interest in the estuary, you are invited to visit our website which carries a wide range of information, including current live weather and Buoy positions, charts, tidal information and copies of this and other Notice to Mariners.

www.humber.com