
NOTICE TO MARINERS

No. H. 28/2017

RIVER HUMBER

HALTON MIDDLE - SHOAL WATER

MARINERS ARE WARNED that surveys carried out on the 27th and 28th February 2017 show the following: -

- 1) Depths of between 4.8 metres and 5.5 metres below Chart Datum have encroached up to 140 metres into the East side of the channel, from 100 metres downstream to 490 metres upstream of the No. 15A Light Buoy.

Deeper water exists to the West in this vicinity.

- 2) Depths of between 4.0 metres and 5.5 metres below Chart Datum have encroached up to 170 metres into the West side of the channel from 90 metres upstream of the No. 12 Killingholme Light Buoy to 550 metres upstream of the No. 14 Skitter Haven Light Buoy.

Deeper water exists to the East in this vicinity.

- 3) Depths of between 4.0 metres and 5.5 metres below Chart Datum have encroached up to 20 metres into the West side of the channel from 100 metres to 630 metres downstream of the No. 18 Elbow Killingholme Light Buoy.

Deeper water exists to the East in this vicinity.

MARINERS ARE ADVISED that Notice to Mariners No. H. 145/2016 and No. H. 10/2017 are hereby cancelled.

**CAPT. A. FIRMAN
HARBOUR MASTER, HUMBER**

6th March 2017

THE INTERNET

In order to widen communication between ABP Humber Estuary Services and those with an interest in the estuary, you are invited to visit our website which carries a wide range of information, including current live weather and Buoy positions, charts, tidal information and copies of this and other Notice to Mariners.
www.humber.com