

---

# NOTICE TO MARINERS

---

No. H. 31/2019

## U P P E R H U M B E R

### S H O A L W A T E R

**MARINERS ARE WARNED** that surveys carried out on the 11<sup>th</sup> and 12<sup>th</sup> March 2019 show the following:

- 1) A least depth of 1.6 metres **ABOVE** Chart Datum exists North of the ships course 280 metres downstream of the Lower Whitton Light Float.

Deeper water exists on and to the South of the ships course in this vicinity.

- 2) A least depth of 0.1 metres **ABOVE** Chart Datum exists North of the ships course 130 metres upstream of the Cappers West Light Float.

Deeper water exists on and to the South of the ships course in this vicinity.

- 3) A least depth of 0 metres at Chart Datum exists South of the ships course 330 metres upstream of the Middle Whitton Light Float.

Deeper water exists on and to the North of the ships course in this vicinity.

- 4) A least depth of 0.4 metres **ABOVE** Chart Datum exists close North of the ships course 365 metres upstream of the No. 32C Light Buoy.

Deeper water exists on the ships course in this vicinity.

- 5) A least depth of 0.1 metres **ABOVE** Chart Datum exists North of the ships course 250 metres upstream of the No. 40 East Walker Dyke Light.

Deeper water exists on the ships course in this vicinity.

**MARINERS ARE ADVISED** that 0.2 metres below Chart Datum should be used for passage planning purposes and Notice to Mariners No. H. 30/2019 is hereby cancelled.

**CAPT. A. FIRMAN  
HARBOUR MASTER, HUMBER**

12<sup>th</sup> March 2019

THE INTERNET

In order to widen communication between ABP Humber Estuary Services and those with an interest in the estuary, you are invited to visit our website which carries a wide range of information, including current live weather and Buoy positions, charts, tidal information and copies of this and other Notice to Mariners.

[www.humber.com](http://www.humber.com)