
NOTICE TO MARINERS

No. H. 36/2017

RIVER HUMBER

HULL ROADS – EAST MIDDLE - SHOAL WATER

MARINERS ARE WARNED that a survey carried out on the 22nd March 2017 shows the following: -

- 1) A least depth of 3.7 metres below Chart Datum exists on the Southern edge of the channel 300 metres upstream of the East Middle Light Buoy.

Deeper water exists to the North in this vicinity.

- 2) Depths of between 3.7 metres and 5.5 metres below Chart Datum have encroached up to 75 metres into the Southern edge of the channel from 142 metres upstream of the No. 22 Hook Light Buoy to 400 metres downstream of the East Middle Light Buoy.

Deeper water exists to the North in this vicinity.

MARINERS ARE ADVISED that Notice to Mariners No. H. 13/2017 is hereby cancelled.

**CAPT. A. FIRMAN
HARBOUR MASTER, HUMBER**

23rd March 2017

THE INTERNET

In order to widen communication between ABP Humber Estuary Services and those with an interest in the estuary, you are invited to visit our website which carries a wide range of information, including current live weather and Buoy positions, charts, tidal information and copies of this and other Notice to Mariners.
www.humber.com