

---

# NOTICE TO MARINERS

---

No. H. 42/2018

## R I V E R H U M B E R

### ALEXANDRA DOCK, HULL – FENDER REPLACEMENT WORKS

**NOTICE IS HEREBY GIVEN** that commencing Tuesday 14<sup>th</sup> March 2018 (or as soon after as circumstances permit) and continuing for a period of one month, fender replacement works will be carried out on the East Inner Approach knuckle at Alexandra Dock, Hull.

**MARINERS ARE REQUESTED** to line up for the lock using the fenders to the West on arrival and departure at Alexandra Dock, Hull **AND ARE FURTHER REQUESTED** to avoid the East Inner Approach knuckle.

**CAPT. A FIRMAN  
HARBOUR MASTER, HUMBER**

14<sup>th</sup> March 2018

THE INTERNET

In order to widen communication between ABP Humber Estuary Services and those with an interest in the estuary, you are invited to visit our website which carries a wide range of information, including current live weather and Buoy positions, charts, tidal information and copies of this and other Notice to Mariners.

[www.humber.com](http://www.humber.com)