

---

# NOTICE TO MARINERS

---

No. H. 61/2017

## RIVER HUMBER

### HESSLE SAND - SHOAL WATER

**MARINERS ARE WARNED** that a survey carried out on the 18<sup>th</sup> May 2017 shows the following:-

- 1) A least depth of 0.3 metres **ABOVE** Chart Datum exists close North of the ships course 700 metres downstream of the No. 28A Light Float.

Deeper water exists to the South in this vicinity.

**MARINERS ARE ADVISED** that the shoal water referred to in Notice to Mariners No. H. 41/2017 is no longer valid and 0.3 metres **ABOVE** Chart Datum should be used for passage planning.

**CAPT. A. FIRMAN**  
**HARBOUR MASTER, HUMBER**

19<sup>th</sup> May 2017

THE INTERNET

In order to widen communication between ABP Humber Estuary Services and those with an interest in the estuary, you are invited to visit our website which carries a wide range of information, including current live weather and Buoy positions, charts, tidal information and copies of this and other Notice to Mariners.

[www.humber.com](http://www.humber.com)