

---

# NOTICE TO MARINERS

---

No. H. 64/2016

## UPPER HUMBER

### MOVES OF FLOATING MARKS AND SHOAL WATER

**NOTICE IS HEREBY GIVEN** that it is proposed on Thursday 9<sup>th</sup> June 2016 (or as soon after as circumstances permit) to move:-

- 1) The No. 33 Light Float to a position 107° T., 1765 metres from the Whitton Ness Beacon.

Latitude 53° 42.577' N, Longitude 0° 35.109' W (WGS 84)

- 2) The No. 32B Light Float to a position 355° T., 832 metres from the Whitton Ness Beacon.

Latitude 53° 43.303' N, Longitude 0° 36.713' W (WGS 84)

- 3) The No. 34 Light Buoy to a position 276° T., 2360 metres from the Whitton Ness Beacon.

Latitude 53° 42.978' N, Longitude 0° 38.779' W (WGS 84)

The No. 33 Light Float will then bear 338° T., 909 metres from the Cappers West Light Float and 134° T., 926 metres from the Middle Whitton Light Float.

The No. 32B Light Float will then bear 303° T., 1305 metres from the Middle Whitton Light Float and 089° T., 889 metres from the Upper Whitton Light Float.

The No. 34 Light Buoy will then bear 238° T., 645 metres from the No. 32C Light Buoy and 028° T., 1275 metres from the No. 40 East Walker Dyke Light.

**MARINERS ARE WARNED** that on completion of the above moves the following shoal water will exist:-

- 1) A least depth of 0.3 metres below Chart Datum exists South of the ships course from 120 metres to 480 metres upstream of the No. 32B Light Float.

Deeper water exists on and to the North of the ships course in this vicinity.

- 2) A least depth of 0.5 metres below Chart Datum exists on the ships course in the vicinity of the No. 32B Light Float.

Deeper water exists to the North of the ships course in this vicinity.

- 3) A least depth of 0.5 metres below Chart Datum exists close South of the ships course from 520 metres to 715 metres downstream of the No. 40 East Walker Dyke Light.

Deeper water exists on and to the North of the ships course in this vicinity.

**MARINERS ARE ADVISED** that on completion of the above moves 0.3 metres below Chart Datum should be used for passage planning purposes and Notice to Mariners No. H. 63/2016 will be cancelled.

**CAPT. A. FIRMAN  
HARBOUR MASTER, HUMBER**

8<sup>th</sup> June 2016

**THE INTERNET**

In order to widen communication between ABP Humber Estuary Services and those with an interest in the estuary, you are invited to visit our website which carries a wide range of information, including current live weather and Buoy positions, charts, tidal information and copies of this and other Notice to Mariners.

[www.humber.com](http://www.humber.com)