

---

# NOTICE TO MARINERS

---

No. H. 70/2018

## U P P E R H U M B E R

### MOVES OF FLOATING MARKS AND SHOAL WATER

**NOTICE IS HEREBY GIVEN** that it is proposed on Saturday 5<sup>th</sup> May 2018 (or as soon after as circumstances permit) to move: -

- 1) The Middle Whitton Light Float to a position 095° T., 867 metres from Whitton Ness Beacon.

Latitude 53° 42.815' N, Longitude 0° 35.856' W (WGS 84)

(83 metres West of its current position)

- 2) The No. 33A Light Float to a position 028° T., 1149 metres from the Whitton Ness Beacon.

Latitude 53° 43.405' N, Longitude 0° 36.155' W (WGS 84)

(151 metres South South West of its current position)

- 3) The No. 32C Light Buoy to a position 278° T., 1279 metres from the Whitton Ness Beacon.

Latitude 53° 42.947' N Longitude 0° 37.794' W (WGS 84)

(112 metres South of its current position)

The Middle Whitton Light Float will then bear 314° T., 1638 metres from the No. 33 Light Float.

The No. 33A Light Float will then bear 343° T., 1142 metres from the new position of the Middle Whitton Light Float and 100° T., 625 metres from the No. 32B Light Float.

The No. 32C Light Buoy will then bear 217° T., 1186 metres from the Upper Whitton Light Float and 060° T., 688 metres from the No. 34 Light Buoy.

**MARINERS ARE WARNED** that on completion of the above moves, the following shoal water will exist: -

- 1) A least depth of 0.2 metres below Chart Datum exists close North of the ships course 315 metres downstream of the Lower Whitton Light Float.

Deeper water exists on and to the South of the ships course in this vicinity.

- 2) A least depth of 0.1 metres **ABOVE** Chart Datum exists North of the ships course 354 metres upstream of the No. 32C Light Buoy.

Deeper water exists on the ships course in this vicinity.

**MARINERS ARE ADVISED** that on completion of the above moves, 0 metres at Chart Datum should be used for passage planning purposes and Notice to Mariners No. H. 69/2018 will be cancelled.

**CAPT. A. FIRMAN  
HARBOUR MASTER, HUMBER**

2<sup>nd</sup> May 2018

**LOCAL NOTICE TO MARINERS FOR 2012, 2014, 2015, 2017 & 2018 CURRENTLY IN FORCE:**

H. 15/2012, H. 50/2014, H. 42/2015, **H. 83/2017**, H. 94/2017, H. 103/2017, H. 149/2017, H. 158/2017, **H. 163/2017**, H. 02/2018, H. 09/2018, H. 16/2018, H. 23/2018, **H. 25/2018**, H. 26/2018, H. 41/2018, **H. 47/2018**, **H. 48/2018**, H. 52/2018, H. 53/2018, H. 54/2018, **H. 57/2018**, H. 59/2018, **H. 62/2018**, H. 63/2018, H. 64/2018, H. 65/2018, H. 66/2018, H. 67/2018, H. 68/2018, H. 69/2018, **H. 70/2018**

**THE INTERNET**

In order to widen communication between ABP Humber Estuary Services and those with an interest in the estuary, you are invited to visit our website which carries a wide range of information, including current live weather and Buoy positions, charts, tidal information and copies of this and other Notice to Mariners.

[www.humber.com](http://www.humber.com)