

# NOTICE TO MARINERS

---

No. H. 73/2016

## RIVER HUMBER

### SKITTER CHANNEL - SHOAL WATER

**MARINERS ARE WARNED** that surveys carried out on the 28<sup>th</sup> to 30<sup>th</sup> June 2016 show the following:-

A Least Depth of 0.9 metres below Chart Datum exists North of the ships course 65 metres upstream of the No. 21A Light Buoy.

Deeper water exists to the South in this vicinity.

**MARINERS ARE ADVISED** that 1.0 metres below Chart Datum should be used for passage planning purposes and that Notice to Mariners H.51/2016 is hereby cancelled

**CAPT. A. FIRMAN  
HARBOUR MASTER, HUMBER**

1<sup>st</sup> July 2016

**THE INTERNET**

In order to widen communication between ABP Humber Estuary Services and those with an interest in the estuary, you are invited to visit our website which carries a wide range of information, including current live weather and Buoy positions, charts, tidal information and copies of this and other Notice to Mariners.

[www.humber.com](http://www.humber.com)