

# NOTICE TO MARINERS

---

No. H. 81/2018  
**U P P E R H U M B E R**  
**S H O A L W A T E R**

**MARINERS ARE WARNED** that surveys carried out on the 17<sup>th</sup> and 18<sup>th</sup> of May 2018 show the following: -

- 1) A least depth of 0.4 metres **ABOVE** Chart Datum exists close North of the ships course 331 metres downstream of the Lower Whitton Light Float.

Deeper water exists on and to the South of the ships course in this vicinity.

- 2) A least depth of 0.4 metres **ABOVE** Chart Datum exists close South of the ships course 200 metres downstream of the No. 32B Light Float.

Deeper water exists on and to the North of the ships course in this vicinity.

- 3) A least depth of 0.5 metres **ABOVE** Chart Datum exists close North of the ships course 350 metres upstream of the No. 32C Light Buoy.

Deeper water exists on the ships course in this vicinity.

**MARINERS ARE ADVISED** that 0.4 metres **ABOVE** Chart Datum should be used for passage planning purposes and Notice to Mariners No. H. 80/2018 is hereby cancelled.

**MARINERS ARE FURTHER ADVISED** that buoy moves are planned for Wednesday 23<sup>rd</sup> May 2018, detailed information will be provided in a further Notice to Mariners.

**CAPT. A. FIRMAN**  
**HARBOUR MASTER, HUMBER**

18th May 2018

**THE INTERNET**

In order to widen communication between ABP Humber Estuary Services and those with an interest in the estuary, you are invited to visit our website which carries a wide range of information, including current live weather and Buoy positions, charts, tidal information and copies of this and other Notice to Mariners.

[www.humber.com](http://www.humber.com)